


To Check Diodes

Tools Needed: Multimeter Set At Ω HMS X 1000

Note: Before Proceeding Disconnect At Least One Lead From The Diode Being Tested.

Procedure: Touch 1 Lead Of The Meter To The Threaded Stud Of The Diode And The Other To The Terminal Connecting Post. Observe The Meter. Switch Position Of The Meter Leads. Observe The Meter. Continuity In Both Directions, Or Neither Direction Indicates A Defective Diode. Replace The Diode.



SENTRY BATTERY CHARGERS - DIODE TESTING
MARINE DEVELOPMENT CORP.

| | | |
|---------------|---------------|----------------|
| SCALE: NONE | DRAWN BY: REL | DRAWING NUMBER |
| DATE: 1/24/96 | REVISED: | SKA-622 |